# 16 Clifton Terrace

BH2019/02367 & 8




## **Application Description**

Rebuilding of random rubble, brick and flint garden wall in lime mortar to the rear of the site.



## **Location Plan**





## Aerial photo(s) of site




## 3D Aerial photo of site





## **Block Plan**





## Photos of the site



Boundary Wall prior to demolition



## Photos of the site



Temporary Wall instated at the time of the initial site visit



## Photos of the site







Examples of flint-work along Vine Place




# **Pre-Existing Front Elevation**



## **Proposed Front Elevation**




## **Pre-Existing Rear Elevation**




469/300 D

## **Proposed Rear Elevation**



469/300 D

#### **Site Section**




Typical Section A-A (1:50)





## **Site Sections**





# **Key Considerations in the Application**

- The impact on the Listed Buildings and conservation area from the existing condition
- Benefits of reinstating a high quality replacement flint wall



## **Conclusion and Planning Balance**

 The existing condition of the site is causing harm to the historical significance of the host building and wider conservation area; the reinstatement of the flint wall will be of great benefit to the character and appearance of the site.