

+44(0)7811405965

10<sup>th</sup>, Aug-16

Mr. Mohammad ABDOLHKANI,  
BARCODE RESTAURENT-CAFE-BAR  
128 Church Road,  
Hove, East Sussex  
BN3 2EA

Dear Sir,

RE; Main Kitchen Extraction and Fresh Air Intake Motor units noisy operation.

Further to my inspection and work carried out during the first week of August-2016, main cause of sound source was your Fresh Air Intake unit which it had slightly noisy shaft bearing.

Hence the whole fan unit it has been condemned and replaced with new Water Cooled Air conditioner.

Furthermore, a new Inverter frequency speed control was introduced as the old controller choice was under rated for the extractor fan in operation, and set at 40 Hz, running as requested.

I hope all the works carried out are up to your satisfaction and please do not hesitate to contact us if in any way assistant needed.

Yours Faithfully,

  
S. Mahin,

For and on behalf of

City Electrical Services.



FAN CONTROLLER  
Box





FAN SHOWS . REMOTE  
CONTROLLER





OLD INTAKE  
CONDEMNED  
REPLACED